



**BACHE ONE ALPHA DEPARTURE (BACHE 1A):** AFTER DEPARTURE, MAINTAIN RWY HEADING CLIMB TO 500M, TURN RIGHT TO VDO/DME, CONTINUE TURNING RIGHT TO PASSING 1850M OR ABOVE AT BACHE.

**DOCHU ONE ALPHA DEPARTURE (DOCHU 1A):** AFTER DEPARTURE, MAINTAIN RWY HEADING CLIMB TO 500M, TURN RIGHT TO VDO/DME, CONTINUE TURNING RIGHT TO PASSING 1850M OR ABOVE AT DOCHU.

**HALAM ONE ALPHA DEPARTURE (HALAM 1A):** AFTER DEPARTURE, MAINTAIN RWY HEADING CLIMB TO 500M, TURN RIGHT TO VDO/DME, CONTINUE TURNING RIGHT TO PASSING 1200M OR ABOVE AT HALAM.

**CATBA ONE ALPHA DEPARTURE (CATBA 1A):** AFTER DEPARTURE, MAINTAIN RWY HEADING CLIMB TO 500M, TURN RIGHT TO VDO/DME, CONTINUE TURNING RIGHT TO PASSING 1200M OR ABOVE AT CATBA.